

GB717 - Caterpillar

STATUS

På lager

REF. NR.

GB717

MANUFACTURE

Caterpillar

TYPE

7241

RED.

4,5:1

HP IND

1400

RPM IND

1125

FABRIKS NR.

36W305

VESSEL

Vos Siren

REMARKS

Oilpump missing (broken)



CATERPILLAR

REG. U.S. PAT. OFF.

MARINE REVERSE AND REDUCTION GEAR

MODEL NO.	SERIAL NO.	RATIO	OIL CAP.	RATING	HP	SM
77F	101405	4.1:1	3 GALS.	CONT.	100	4

GIVE MODEL NUMBER AND SERIAL NUMBER WHEN ORDERING PARTS

LUBRICATION

EVERY 10 SERVICE HOURS: CHECK OIL LEVEL IN GEAR COMPARTMENT. OIL SHOULD BE UP TO THE FOLD MARK ON THE GAUGE WITH ENGINE RUNNING AND CLUTCH ENGAGED.

EVERY 125 SERVICE HOURS OR WHEN VESSEL IS DOCKED: LUBRICATE OUTPUT SHAFT SEAL WITH WATER INSOLUBLE WATER BUMP GREASE AND REMOVE AND CLEAN THE WEATHER-STRIP HOUSING WITH SAE 30-WT. CRANKCASE LUBRICATING OIL. REMOVE AND REPLACE FILTER ELEMENT AT EACH OIL CHANGE.

MANUFACTURED BY
CATERPILLAR TRACTOR CO.
PEORIA, ILLINOIS
MADE IN U.S.A.

4L4233