

# Caterpillar - 7241

STATUS	På lager
REF. NR.	GB717
MANUFACTURE	Caterpillar
TYPE	7241
RED.	4,5:1
HP IND	1400
RPM IND	1125
FABRIKS NR.	36W305
VESSEL	Vos Siren
REMARKS	Oilpump missing (broken)





**CATERPILLAR**

REG. U.S. PAT. OFF.

**MARINE REVERSE AND REDUCTION GEAR**

MODEL NO. SERIAL NO. RATIO OIL CAP. RATING RPM

777 101205 4.1:1 30 GALS. CONT. 1500

GIVE MODEL NUMBER AND SERIAL NUMBER WHEN ORDERING PARTS

**LUBRICATION**

EVERY 10 SERVICE HOURS: CHECK OIL LEVEL IN GEAR COMPARTMENT. OIL SHOULD BE UP TO THE FOLD MARK ON THE GAUGE WITH ENGINE RUNNING AND CLUTCH ENGAGED.  
EVERY 125 SERVICE HOURS OR WHEN VESSEL IS DOCKED: LUBRICATE OUTPUT SHAFT SEAL WITH WATER INSOLUBLE WATER BUMP GREASE AND REMOVE AND CLEAN THE BREATHER.  
EVERY 1000 SERVICE HOURS: DRAIN, WASH AND RE-FILL HOUSING WITH S.A.E. 30-WT. CRANKCASE LUBRICATING OIL. REMOVE AND REPLACE FILTER ELEMENT AT EACH OIL CHANGE.

MANUFACTURED BY  
**CATERPILLAR TRACTOR CO.**  
PEORIA, ILLINOIS  
MADE IN U.S.A. 414233