

T203 - Liaaen

STATUS

Available

REF. NUMBER

T203

MANUFACTURE

Liaaen

TYPE

TCN83/59-210 No. 1921

YEAR

1982



Emergency Steering Procedures

1. Ensure engine room has control.
2. Set steering and pitch to emergency on the bridge.
3. Set engine room control to engine room.
4. Open the red valve on starboard side of thrusters unit (marked with arrow) for emergency pitch controls. (Diagram 1)
5. Move red knob for pitch. Right for ahead, Left for astern. (Diagram 1)
6. Push lever on port side railings for steering. Forward for starboard, Aft for Port. (Diagram 2)




Diagram 1




Diagram 2



